

R_DE

| | REF / ART.NR | | ABMESSUNGEN | | | | DRUCKBELASTUNG | |
|---|--------------|----|-------------|----|------|----|----------------|----------|
| | | Sh | ØA | B | D | C | LAST | FEDERWEG |
| | | | mm. | | | | kg. | mm. |
| R | R1215 | 60 | 12 | 15 | M-05 | 10 | 15 | 3,0±0,5 |
| | R1610 | 60 | 16 | 10 | M-05 | 12 | 20 | 1,5±0,5 |
| | R1615 | 60 | 16 | 15 | M-05 | 12 | 15 | 2,5±0,5 |
| | R1620 | 60 | 16 | 20 | M-05 | 12 | 15 | 3,5±0,5 |
| | R1625 | 60 | 16 | 25 | M-05 | 12 | 15 | 4,5±1,0 |
| | R2008 | 60 | 20 | 8 | M-06 | 15 | 45 | 1,6±0,5 |
| | R2015 | 60 | 20 | 15 | M-06 | 15 | 35 | 3,0±0,5 |
| | R2020 | 60 | 20 | 20 | M-06 | 15 | 25 | 4,0±1,0 |
| | R2025 | 60 | 20 | 25 | M-06 | 15 | 25 | 5,0±1,0 |
| | R2030 | 60 | 20 | 30 | M-06 | 15 | 25 | 6,0±1,0 |
| | R2510 | 50 | 25 | 10 | M-08 | 20 | 50 | 2,0±0,5 |
| | R2515 | 50 | 25 | 15 | M-08 | 20 | 40 | 3,0±0,5 |
| | R2520 | 50 | 25 | 20 | M-08 | 20 | 40 | 4,0±0,5 |
| | R2525 | 50 | 25 | 25 | M-08 | 20 | 40 | 5,0±1,0 |
| | R2530 | 50 | 25 | 30 | M-08 | 20 | 40 | 6,0±1,0 |
| | R2540 | 50 | 25 | 40 | M-08 | 20 | 40 | 8,0±1,0 |
| | R2822 | 50 | 28 | 22 | M-08 | 20 | 60 | 5,0±1,0 |
| | R3010 | 50 | 30 | 10 | M-08 | 20 | 80 | 2,0±0,5 |
| | R3015 | 50 | 30 | 15 | M-08 | 20 | 80 | 3,0±0,5 |
| | R3020 | 50 | 30 | 20 | M-08 | 20 | 80 | 4,0±0,5 |
| | R3030 | 50 | 30 | 30 | M-08 | 20 | 60 | 6,0±1,0 |
| | R3040 | 50 | 30 | 40 | M-08 | 20 | 60 | 8,0±1,0 |
| | R4020M8X20 | 50 | 40 | 20 | M-08 | 20 | 140 | 4,0±0,5 |
| | R4020 | 50 | 40 | 20 | M-10 | 25 | 140 | 4,0±0,5 |
| | R4028M8X20 | 50 | 40 | 28 | M-08 | 20 | 100 | 5,5±1,0 |
| | R4028 | 50 | 40 | 28 | M-10 | 25 | 100 | 5,5±1,0 |
| | R4035 | 50 | 40 | 35 | M-10 | 25 | 100 | 7,0±1,0 |
| | R4040M8X20 | 50 | 40 | 40 | M-08 | 20 | 100 | 8,0±1,0 |
| | R4040 | 50 | 40 | 40 | M-10 | 25 | 100 | 8,0±1,0 |
| | R4045 | 50 | 40 | 45 | M-10 | 25 | 90 | 9,0±1,0 |
| | R5020 | 50 | 50 | 20 | M-10 | 25 | 300 | 4,0±0,5 |
| | R5025 | 50 | 50 | 25 | M-10 | 25 | 175 | 5,0±1,0 |
| | R5030 | 50 | 50 | 30 | M-10 | 25 | 160 | 6,0±1,0 |
| | R 5035 | 50 | 50 | 35 | M-10 | 25 | 160 | 7,0±1,0 |
| | R5040 | 50 | 50 | 40 | M-10 | 25 | 155 | 8,0±1,0 |
| | R5045 | 50 | 50 | 45 | M-10 | 25 | 150 | 9,0±1,0 |
| | R5060 | 50 | 50 | 60 | M-10 | 25 | 130 | 12,0±1,5 |
| | R6025 | 50 | 60 | 25 | M-10 | 25 | 400 | 5,0±1,0 |
| | R6035 | 50 | 60 | 35 | M-10 | 25 | 300 | 7,0±1,0 |
| | R6045 | 50 | 60 | 45 | M-10 | 25 | 250 | 9,0±1,0 |
| | R6060 | 50 | 60 | 60 | M-10 | 25 | 225 | 12,0±1,5 |
| | R7035M10X25 | 50 | 70 | 35 | M-10 | 25 | 450 | 7,0±1,0 |
| | R7040M10X25 | 50 | 70 | 40 | M-10 | 25 | 400 | 8,0±1,0 |
| | R7050M10X25 | 50 | 70 | 50 | M-10 | 25 | 300 | 10,0±1,0 |
| | R 070M10X25 | 50 | 70 | 70 | M-10 | 25 | 300 | 14,0±1,5 |
| | R7035 | 50 | 70 | 35 | M-12 | 33 | 450 | 7,0±1,0 |
| | R7040 | 50 | 70 | 40 | M-12 | 33 | 400 | 8,0±1,0 |
| | R7050 | 50 | 70 | 50 | M-12 | 33 | 300 | 10,0±1,0 |
| | R7070 | 50 | 70 | 70 | M-12 | 33 | 300 | 14,0±1,5 |
| | R7525 | 50 | 75 | 25 | M-12 | 33 | 650 | 5,0±1,0 |
| | R8030 | 50 | 80 | 30 | M-14 | 35 | 950 | 6,0±1,0 |
| | R8040 | 50 | 80 | 40 | M-14 | 35 | 600 | 8,0±1,0 |
| | R8055 | 50 | 80 | 55 | M-14 | 35 | 500 | 11,0±1,5 |
| | R9525 | 60 | 95 | 25 | M-16 | 42 | 1800 | 5,0±1,0 |
| | R9540 | 50 | 95 | 40 | M-16 | 42 | 1000 | 8,0±1,0 |

